

SERVICE BULLETIN 122

SUBJECT: Navigation Antenna Length

APPLICATION: All Navigation Antennas shipped between 12/2/92 and 2/1/93.

DESCRIPTION: It has come to our attention that several of our NAV antennas that were shipped during the time period given above, may have had their copper foils cut considerably too long. The foils that were trimmed too long were at least twice the length they should have been and would have been difficult to install into the existing structure.

SOLUTION: Before installation, trim each copper foil strip to 24" \pm 1/8" long. If however you have already installed your antenna, carefully remove the laminate that covers the copper foil strips outboard of the 24 inches, and trim off the foil. As an alternative, removing 1" or 2" outboard of the 24" point will accomplish the same affect.



MODEL	ASSEMBLY NAME	REVISION	DATE	VOLUME	PAGE
GLASAIR	SERVICE BULLETIN 122		11/18/93		1 of 1