

SERVICE BULLETIN 7A

SUBJECT: WELDS ON INBOARD RIB ATTACH BRACKETS INTERFERE WITH WASHERS

APPLICATION: Service Bulletin 7A applies to the first production run (the first fifty sets) of Glasair FT landing gear hardware. This is all the landing gear hardware that has been shipped to date.

DESCRIPTION: When the welds in the inboard rib attach bracket that were referenced in Service Bulletin 7 have been completed, they will interfere with the AN970-4 washers installed on the inboard strut attach bracket assembly. See FIGURE (B-19) on page B-30 of the Glasair FT Instruction Appendix.

SOLUTION: Use the enclosed MS27183-11 washers in place of the AN970-4 washers called out in FIGURE (B-19) on page B-30 of the Glasair FT Instruction Appendix.



MODEL	ASSEMBLY NAME	REVISION	DATE	VOLUME	PAGE
GLASAIR FT	SERVICE BULLETIN 7A		10/31/85		1