

SERVICE BULLETIN 8

SUBJECT: DEFECTIVE FUEL FITTINGS

APPLICATION: Service Bulletin 8 applies to complete Glasair kits and Glasair fuel system kits shipped during the months of August through October of 1985.

DESCRIPTION: We have been advised by the manufacturer that the AC6470069 fittings included with your fuel system kit may be defective due to insufficient wall thickness.

SOLUTION: Destroy the AC6470069 fittings that were shipped with your kit to ensure that they are never used in an aircraft fuel system. Enclosed are replacement AC6470069 fittings which should be used in place of the fittings that were shipped with your kit.

Thank you for your attention to this matter.

 STODDARD-HAMILTON AIRCRAFT, INCORPORATED					
MODEL	ASSEMBLY NAME	REVISION	DATE	VOLUME	PAGE
GLASAIR	SERVICE BULLETIN 8		11/13/85		1