

GLASTAR SERVICE LETTER 3


Subject: Trim cable bracket angle (P/N 303-00020-01) and sheet (P/N 303-00021-01)

Applicability: Kits #5001–5467

Discussion: Due to a parts list error, the trim cable bracket angle and trim cable bracket sheet, two parts required for the manual trim system installation in the elevator, were not included in early tail kit shipments. Instead, these parts were included in the manual trim system kit, typically shipped with the fuselage kit. These parts, however, must be installed during construction of the elevator, which is why they were intended to be standard parts in the tail kit. The parts are called out in Steps 15–19 of *Assembly Manual* "SECTION V: ELEVATOR ASSEMBLY."

If you received a tail kit without these two parts **and** you are intending to install the manual elevator trim system, please contact Option Sales by no later than **July 31, 1997**, to request these parts. They will be shipped to you at no charge. However, if you order these parts after July 31, 1997, you may be responsible for the cost of the parts and/or shipping costs, at our discretion.

If you are installing the optional electric elevator trim system, you have no need of these parts.

 <p>STODDARD-HAMILTON AIRCRAFT INCORPORATED</p>	REVISION:	DATE: 6/30/97	PAGE: 1 of 1
----------------------------------------------------------------------------------------------------------------------------------------	-----------	------------------	-----------------