

SERVICE BULLETIN 37

SUBJECT: Glasair II Lower Wing Panel With Glasair III Wheelwell Scribe Lines

APPLICATION: All Glasair II kits delivered prior to 6/16/87.

DESCRIPTION: The Glasair II wings are produced in the same mold as the Glasair III wings. The raised scribe marks for the Glasair III wheelwell cutouts were inadvertently incorporated on the Glasair II lower wing panels produced before 6/16/87. These scribe lines are incorrect for the Glasair II wing assembly.

SOLUTION: These incorrect scribe lines should be ignored and sanded off the Glasair II lower wing panels. Glasair II RG kits will be supplied with a template for the wheelwell cutout.



MODEL	ASSEMBLY NAME	REVISION	DATE	VOLUME	PAGE
GLASAIR	SERVICE BULLETIN 37		06/25/87		1