


SERVICE LETTER 8

**SUBJECT: REMINDER TO COMPLY WITH GLASAIR III MANDATORY SERVICE BULLETIN 95 SUPPLEMENT "A," REFERRING TO THE LANDING GEAR OLEO STRUT WELD JOINTS.**

**APPLICATION:** Glasair III landing gear struts, serial numbers 051 through 101.

**DESCRIPTION:** SB 95 Supplement "A" issued in August 1991 was a mandatory bulletin to replace all the chrome oleo cylinders on Glasair IIIs with gear strut #s 051 through 101. We still have about 18 sets of oleos in stock indicating that there are many of you who have not complied with this important bulletin. **If you have not replaced your oleo cylinders yet, please do so before August 95.**

**SOLUTION:** We will continue to honor the 1991 price (\$480.00, plus shipping, for three chrome oleo cylinders, seal kits, and service instructions) given in SB 95 Supplement "A" through 8/31/95. Please call our order desk and refer to kit part number 353-5120-501. (Individual oleo and seal kit pricing is available upon request.)

 <b>© STODDARD-HAMILTON</b> AIRCRAFT, INCORPORATED					
MODEL	ASSEMBLY NAME	REVISION	DATE	VOLUME	PAGE
GLASAIR III	SERVICE BULLETIN 8		3/10/95		1 of 1