

Dear Glasair Builders:

Based on feedback from the Builder's Association we are revising the way we handle service bulletin revisions. We will no longer issue a REV to the service bulletin. (E.g. Service Bulletin 44 REV A.) A new service bulletin number will be issued. The new service bulletin will note the service bulletin that it supersedes and list any revisions that were made. We think this will simplify the tracking and application of Service Bulletins.

The advisory publication index is now up to date. This is the best place to start when checking for new advisory publications.

- **Index of Glasair Advisory Publications Rev L**

Please disregard and delete the following service bulletin. It was originally released as applicable to all our product lines – Glasair, GlaStar and Sportsman:

- **Service Bulletin 58: Prop Governor Gasket**

It has been replaced by:

- **Glasair Service Bulletin 159: Prop Governor Gasket**


The content is the same, but we have decided it is best to separate the advisory publications by product line. Our apologies for any confusion this has caused.

In addition,

- **Glasair Service Bulletin 160: Nose Gear axle nut**

has also been released.

Please do not hesitate to contact technical support @ 360-435-8536 or [technicalsupport@glasairaviation.com](mailto:technicalsupport@glasairaviation.com) if you have any questions.

	Model: Glasair	Document: Service Bulletin Rev Memo	Revision: -	Date: 5/7/2007	Page: 1
---	-------------------	---	----------------	-------------------	------------