



Notice Number YYYY-XXX	Safety Alert/ Service Bulletin/ Notification	Release Date MM/DD/YY	Effectivity Date MM/DD/YY	Aircraft Model	Aircraft Serial Number	Subject	Supersedes Notice Number (Enter NA if None)
2016-001	Service Bulletin	05/26/16	05/26/16	M-1	8000	Exchange of stator assy. of Rotax Engine Type 912i (Series) Ref: Rotax SB-912i-006iS	N/A
2016-002	Service Bulletin	06/30/16	06/30/16	M-1	8000	Adjust amount of slack in rudder pedal brake lines to allow free movement, and not cause strain to the brake lines.	N/A
2016-003	Service Bulletin	09/22/16	09/22/16	M-1	8000	Replace radiator mounting hardware and replace nose gear shock pucks as necessary.	N/A
2017-001	Safety Alert	06/27/17	06/27/17	M-1	8000	Ground aircraft for propeller removal and evaluation and general aircraft evaluation. Have engine / gearbox evaluated by engine manufacturer representative. Notify propeller manufacturer of failure.	N/A